



Part No.	Part Description	Material	Repair Part No.		
			LB05	LB07	LB10
1	Plug	304 SS		6L1	
2	O-ring – plug	EPR		5L80	
3	Socket head screw	304 SS		13L65	
4	Casing with plug	304 SS		1L78	
5	O-ring – suction	EPR		5K300	
6	Nozzle/venturi assembly	Lexan® 500		3L20	
7	O-ring guide vane	EPR		5K301	
8	Guide vane	Lexan® 10% G.F.		3K65	
9	Impeller	LB05 4.50" Dia.	2K331		
		LB07 5.00" Dia.		2K829	
		LB10 5.25" Dia.			2K828
10	Mechanical seal – rotary	Carbon	10K110		
11	Mechanical seal – stationary	Ceramic	10K110		
12	O-ring casing	EPR		5K193	
13	Motor adapter with inserts	Amodel® 45% G.F.		1K344	
14	Pipe plug	SAE 1018		6K2	
15	Hex cap screw	Steel (zinc plated)		13K194	
16	Base	Steel		4K399	
17	Grommet	BUNA		4K405	

HP	Motor Codes			
	1Ø – ODP	3Ø – ODP	1Ø – TEFC	3Ø – TEFC
½	SFJ04860R	SFM04873	SFM04821	SFM04876
¾	SJF05860R	SFM05873	SFM05821	SFM05876
1	SFJ06860R	SFM06873	SFM06821	SFM06876